

Auto Draught Tap - Mounting Template

- Please ensure template is printed to scale.
- Place device over template to ensure holes line up.
- Red dashed circles indicated holes to drill.
- 4 x M4 Clearance Holes on device (4.5mm).
- M4 screws or No.8 screw recommended for securing to surface.
- 2 x $\varnothing$ 70mm Services Holes recommended.
- This is a Top view of the mounting plate.

